2019-05-17

441240937

Gabriel Åhbeck

Release Notes MobiMed Smart 4.2.38

Software Article Number:	490212154
Software Build Number:	Release-4.2.38.0_19.05.15.1

Changes specific for Uppsala

- Support Cosmic integration to Uppsala, phase 2 (9704)

Changes specific for Jämtland

- Add missing message template to the minimal report (9862)

General improvements

- Log and warn if two units are using the same license number (9792)
- Support ECG reports for customers without ePR option (9706)



Ortivus AB
P.O. Box 713, 18217 Danderyd, Sweden | Svärdvägen 19, 18253 Danderyd
Telefon:08 446 45 00 | Fax: 08 446 45 19 | info@ortivus.com | www.ortivus.com

- Make it possible to save current GPS coordinate and time stamp easily in Demo ePR (9785)



- Make position icon on map configurable (9861)
- Verify support of Identity Agent 2.2.2.0 (9671)



- Qualify Windows Server 2019 as supported platform (9850)

Fixes

- Correct logged warnings when using SATS triage (9838)
- Camera - Fix issue where comment box was hidden while monitor was active (9774)
- Detection of showing Triage Label should not pollute event log (9782)
- On Windows 10: Login screen should not be displayed when waking up from screen sleep (9787)
- Don't overwrite auto logon domain name for workstations in domains during update (9788)
- MDT - Fix Timestamps from dispatch data being stored in wrong format (9791)
- Load patient ID and name also for closed patients in ECG export (9794)

- Mobilelink - Fix UTC datetime is displayed in MobiMed, should be local (9797)
- Make sure Supervisor can be used on computers with domain auto logon (9851)
- Use log names where date is before process id (9852)
- Alarm initiation fixed to avoid spurious Bradycardia alarms at start-up / cable change (9857)
- SOS Integration: Import Incident time from SOS Pickup time field (9863)
- User should be logged out after handover and if LogoutOnClose is set (9866)
- Manage log application files larger than 32 MB (9714)
- System configurator does not show up in IE after upgrade (9753)
- OSDK - Fix error when setting DoB to today's date (9390)
- MDT - Fix issue where log could contain patient information (9638)

**Numbers in brackets are ID-numbers from Ortivus' work item tracking tool. Numbers starting with "INC" refers to items in ServiceNow.*

Required ePR versions

The functionality in this release requires an the ePR configuration version equal to or later than:

- <ePR Identifier>_4.2.38.0_19.05.15.1

<ePR Identifier> is a text string separating the ePRs among different customers like "Orebro", "SWASFT", etc.

Supported Platforms

Ambulance Unit Hardware	Operating System
Panasonic FZ-M1	Windows 10 (1709)
Panasonic FZ-G1	Windows 10 (1607, 1709, 1809)
Panasonic H2	Windows 7, Windows 8.0
Panasonic CF-19	Windows 7
Getac RX10H Extreme	Windows 10 (1709, 1809)
Getac RX10H	Windows 10 (1511)

All versions of measuring unit M531 are supported with MobiMed 4.2. Measuring unit 300C is not supported.

The Clinical Workstation (CWS) platform should meet or beat the minimum hardware specification and use a supported operating system.

Release Information

This is a commercial release on the following markets:

- Norway
- Sweden
- United Kingdom

This release replaces all previous 4.2 releases.

Upgrade to this release can be done from all previous 4.2 releases.

Ortivus AB
P.O. Box 713, 18217 Danderyd, Sweden | Svärdvägen 19, 18253 Danderyd
Telefon:08 446 45 00 | Fax: 08 446 45 19 | info@ortivus.com | www.ortivus.com